

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Minerals Inspection Report

Reviewed

PHY

08/11/2014 Report Date: Mine Name: Dragon Mine Permit Number: M/023/0080 Mine Status: Active Operator Name: Applied Minerals Inspection Date: 08/07/2014 Permit Fees: Paid Inspector(s): Wayne Western **Bond Amount:** \$199,000 Inspection Time: 9:00 -10:00 Attendee(s): Eric Nedreberg Weather: warm partly cloudy **Bond Escalation:** 06/30/2015 Inspection Purpose: Routine inspection 10/17/2013 **Prior Inspection: Conclusions and Recommendations** The Division should continue to monitor the site and the bond installment. Camera was not working. Evaluated & Commented **Elements of Inspection** Enforcement Permits, Revisions, Transfer, Bonds X Permit fee paid. Operator is on an installment plan for bond increase and on schedule. Public Safety (shafts, adits, trash, signs, highwalls) Operator is rehabilitating an adit. Signs have been posted at the mine entrance to warn public. Protection of Drainages/Erosion Control X No signs of erosion problems. 4. **Deleterious Material** X Trash was handled properly.

Inspector's Signature:

Reclamation

Revegetation

Soils

Other

CC:

5.

6.

7.

8.

9.

10.

 $File: \ /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/M0230080-Dragon/inspect/Insp08072014a.pdf$

Roads (maintenance, surfacing, dust control, safety)

Backfilling/Grading (trenches, pits, roads, highwalls, shafts)

